

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

Campaign No.	Gai-2438	Date	Feb. 21, 2017
Manufacturer	Caterpillar Inc. (Caterpillar Japan LTD.)		
Description of Defect	Fuel hose connecting fill tubes cracks and fuel will leak due to a hose material mismatch.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDS-DYC	「966M」	2015, 2016	4
YDS-JPR	「972M」	2016	1
YDS-N8T	「980M」	2016	5
		TOTAL	10