

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

(Domestic/Import Vehicles)

CAMPAIGN No.	4030	DATE	4,7,2017
MANUFACTURER	KYOKUTO KAIHATSU KOGYO CO., LTD.		
DESCRIPTION OF DEFECT	On some tank semi-trailers ,Because wrong numerical value are written in the braking force column of the data label, this attached to the vehicle body and instruction manual, it is not compliant with safety standards.(Regulation No.13)		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KTT241	tank semi-trailer	2016-2017	3
		TOTAL	3