

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	4091	DATE	Aug 4,2017
MANUFACTURER	TADANO LTD.		
DESCRIPTION OF DEFECT	Based on provisions of Article 55 of the Safety standard, there are some vehicles which received standard relaxation certification of the ground pressure with incorrectly displayed ground pressure because, as a condition of accreditation, the displayed ground pressure unit was incorrect.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDS-T014	TADANO 「GR-160N-4」	2017	35
		TOTAL	35