

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4101	DATE	Sep. 8 2017	
MANUFACTURER	MORITA-ECONOS CORPORATION			
DESCRIPTION OF DEFECT	Concerning driving of Cesspit emptier trucks and Garbage collection trucks, during one-wheel ride (only one wheel is raised and the axle is not parallel to the ground), or during a vehicle turns suddenly, rear tire of a vehicle may hit with a mounting bracket which is used to fix tank or locker box on chassis frame, because of its improper positioning. There is a possibility of damages on rear tire at worst case.			
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
SKG-FEA50	MITSUBISHI FUSO CANTER	2011~2012	11	
TKG-FEA50		2012~2016	17	
TKG-FBA50		2013~2016	42	
TPG-FBA50		2016~2017	11	
TKG-FBA5W	NISSAN ATLAS	2015	1	
TKG-FBA5Y	UD TRUCKS KAZET	2017	1	
			TOTAL	83

※ Vehicle number and production period indicated in a list may includes vehicles which do not have any defect.