

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2598	Date	February 28, 2018
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	In the rear spoiler, due to insufficient adhesive strength between the upper part and the lower part of the spoiler, it may peel off due to the wind pressure during driving. As the result, in the worst case it may fall off then disturb traffic if the vehicle is continuously used as it is.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-3HDJHF	VW Arteon 2.0L	MY2018	2
		Total	2