## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

## Import Vehicles

CAMPAIN No.	Gai –2606	DATE	March 16, 2018
MANUFACTURER	Dr. Ing. h.c. F. Porsche AG		
	(Japanese Importer: Porsche Japan KK)		
DESCRIPTION OF DEFECT	The front wheel and wheel housing liner can come into		
	contact with each other when driving at low speeds		
	combined with significant steering movements, e.g. while		
	maneuvering.		
	This can result in noises and visible superficial abrasion		
	marks on the rear part of the front wheel housing liners.		

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
-991MA175-	911 GT3RS	2016	313
		TOTAL	313