

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/ Vehicles

CAMPAIGN No.	4253	DATE	Apr. 25th, 2018
MANUFACTURER	Yokohama Sharyo Kogyo Co.,Ltd.		
DESCRIPTION OF DEFECT	On the rope hook on the right side of the large shelf mounted on the top of the platform of the tractor, the installation direction is inappropriate, so the full width of the vehicle does not conform to the safety standards the road transport vehicle act.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QKG-EXY52AJ	GIGA	2014	1
QKG-EXY52BJ	GIGA	2015	7
		TOTAL	8