

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4661	DATE	Jan.30 2020
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On the relevant heavy-duty full tractor trucks, the identification label for the rear brake system is missing, because the instruction to attach the label to the 15-liter air tank for the rear brakes was inappropriate.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-FV70HY	「FUSO SUPER GREAT」	2019~2019	4
		TOTAL	4