

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

Campaign No.	Gai-2979	Date	Feb., 6, 2020
Manufacturer	Caterpillar Inc. (Caterpillar Japan LLC)		
Description of Defect	The existing Wave Springs used in the transmission of certain 950M Z and 962M Z Wheel Loaders, can fail and have risk to lose shift control in worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDS-HE8	「950MZ」	2016, 2017	18
YDS-SA8	「962MZ」	2016, 2017	3
		TOTAL	21