## VEHICLE SAFETY / POLLUTION RECALL CAMPAINGN IN JAPAN

## Import Vehicles

CAMPAIGN No.	GAI-2986	DATE	26 <sup>th</sup> Feb 2020	
MANUFACTURE	Triumph Motorcycles Limited			
	(Japanese Importer : Triumph Motorcyces Japan K.K. )			
DESCRIPTION OF				
DEFECT	The Quickshifter Assembly, TSA body may come into contact with the gear change Linkage Clamp			
	Assembly, potentially impeding a smooth "assisted" gear change resulting in a missed gear or false			
	neutral. If this condition occurs, it may lead to a loss of acceleration.			

2BL-N5J1050	Speed Triple RS	2018–2019	205
		TOTAL	205