

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN NO.	4686	DATE	March 11 ,2020
MANUFACTURER		ISUZU BODY CORPORATION	
DESCRIPTION OF DEFECT		On some medium-duty training vehicles, due to the large rear reflector improperly attached position, the geometric visibility may fail to conform to Article 38-2 (large rear reflectors) of the safety standards under Road Transport Vehicle Act.	

TYPE	COMMERCIAL NAME	MODELYEAR RECALLED	NUMBER OF VEHICLE
SKG-FSR90S2	ISUZU "FORWARD"	2016~2017	15
SPG-FSR90S2		2016~2017	5
2RG-FSR90S2		2018	7
2PG-FSR90S2		2017~2019	16
		TOTAL	43