

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4773	DATE	Jul. 8. 2020
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain automatic transmissions, due to the inappropriate shift control program, the forward clutch may become in the half-clutch state when the idle-up control is activated while the vehicle is stopped in the D position. Therefore, the clutch may be abnormally worn out and the strainer area of the oil suction port is possibly clogged with abrasion powder, causing the hydraulic pressure in the automatic transmission to lower, which would allow the warning light to be illuminated and the vehicle unable to run.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2RG-XZC600T	[HINO Dutro]	2019	65
2RG-XZC605M		2017~2019	2,869
TPG-XZC605M			
TPG-XZC605Y			
TPG-XZC610T		2017~2019	910
TPG-XZC630T		2017~2019	15
2RG-XZC645M		2017~2019	650
TPG-XZC645M			
2RG-XZC655M		2017~2019	639
TPG-XZC655M			
2RG-XZC710M		2017~2019	892
TPG-XZC710M			
2RG-XZU600E		2017~2019	2,511
2RG-XZU600T			
2RG-XZU600X			
TPG-XZU600E			
TPG-XZU600M			
TPG-XZU600X			
2RG-XZU605M	2017~2019	2,236	
2RG-XZU605X			
TPG-XZU605M			
TPG-XZU610T	2017~2019	199	
TPG-XZU620T	2017~2019	575	
2RG-XZU640M	2017~2019	305	
TPG-XZU640M			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
TPG-XZU642F	[HINO Dutro]	2017~2019	34	
2RG-XZU645M TPG-XZU645M		2017~2019	692	
2RG-XZU650M TPG-XZU650M		2017~2019	442	
2PG-XZU652F		2019	2	
2RG-XZU655M TPG-XZU655M		2017~2019	1,524	
2KG-XZU700M 2RG-XZU700M TPG-XZU700M		2017~2019	110	
2PG-XZU702X 2RG-XZU702M TPG-XZU702M		2017~2019	78	
2KG-XZU710M 2RG-XZU710M TPG-XZU710M		2017~2019	960	
2PG-XZU712M 2RG-XZU712M TPG-XZU712M		2017~2019	1,226	
2KG-XZU720M 2RG-XZU720M TPG-XZU720M		2017~2019	283	
2PG-XZU722M 2RG-XZU722M TPG-XZU722M		2017~2019	416	
2RG-XZC600D		[Toyota Dyna200]	2019	8
2RG-XZC605 TPG-XZC605 TPG-XZC605V		[Toyota Dyna300] [Toyota Dyna400]	2017~2019	1,449
TPG-XZC610D		[Toyota ToyoaceG25] [Toyota ToyoaceG35]	2017~2019	66
TPG-XZC630D		[Toyota ToyoaceG45]	2017~2019	2
2RG-XZC645 TPG-XZC645		2017~2019	268	
2RG-XZC655 TPG-XZC655		2017~2019	172	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2RG-XZC710 TPG-XZC710	[Toyota Dyna200] [Toyota Dyna300]	2017~2019	130
2RG-XZU600D 2RG-XZU600H TPG-XZU600 TPG-XZU600A TPG-XZU600H	[Toyota Dyna400] [Toyota ToyoaceG25] [Toyota ToyoaceG35] [Toyota ToyoaceG45]	2017~2019	194
2RG-XZU605 2RG-XZU605A TPG-XZU605		2017~2019	1,521
TPG-XZU610D		2017~2019	11
TPG-XZU620D		2017~2019	126
2RG-XZU640 TPG-XZU640		2017~2019	76
2RG-XZU645 TPG-XZU645		2017~2019	415
2RG-XZU650 TPG-XZU650		2017~2019	17
2PG-XZU652W		2019	1
2RG-XZU655 TPG-XZU655		2017~2019	596
2KG-XZU700 2RG-XZU700 TPG-XZU700		2017~2019	56
TPG-XZU702		2017~2019	6
2KG-XZU710 2RG-XZU710 TPG-XZU710		2017~2019	655
2RG-XZU712 TPG-XZU712		2017~2019	377
2KG-XZU720 2RG-XZU720 TPG-XZU720		2017~2019	120
2RG-XZU722 TPG-XZU722		2017~2019	166
		TOTAL	24,065