

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	Gai-3062	DATE	July 28, 2020
MANUFACTURE	DS Automobiles (Japanese Importer : Groupe PSA Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	On affected vehicles, coolant water may leak from the joint between degassing tank and degassing pipe due to lager diameter of hole at the degassing tank. In the worst cases, the leakage may cause illumination of water temperature waning light and engine overheating.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BA-D34HN05	DS 3 Crossback	2019	497
	TOTAL		497