

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-3056	DATE	August 4, 2020
MANUFACTURER	Bentley Motors Limited (Japanese Importer : Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	On a joint of a fuel line in the engine compartment, the heat resistance of the joint is not sufficient due to inadequate evaluation of heat resistance. Therefore, the joint material will be deteriorated by high temperature in the engine compartment and a crack could be created, in the worst case, fuel may leak.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
ABA-BADCU	Bentayga V8	2018 – 2020	268