

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3092	DATE	Sep. 15 2020
MANUFACTURER	Mercedes-Benz (Japanese importer : Mitsubishi Fuso Truck and Bus Corporation)		
DESCRIPTION OF DEFECT	On some articulated buses, due to the inappropriate control program in the axle modulator for the center axle, the temperature around the valve seat of the air on-off valve inside the modulator may become excessive, and the valve seat may be damaged during use impairing the airtightness. As a result, air may leak to the brake chamber side, and a braking force may be generated even when the brakes are not applied.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
Unclear model	「Citaro-G」	2009～2012	23
TOTAL			23