VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic /Import Vehicles

CAMPAIGN No.	Gai-3098	DATE	2/0ctober/2020		
MANUFACTURER	Automobiles Volvo Car Corporation				
	(Japanese Importer: Volvo Car Japan Limited)				
DESCRIPTION OF DEFECT	Filling coolant into the engine cooling system e.g. without using coolant filling vacuum tool or by using a defect coolant filling vacuum tool, could possess a risk for trapped air in the cooling system which might result in insufficient cooling of the engine components. Overheating of engine components which may result in damaged engine components and in rare conditions also cause fire in the engine bay.				

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED		NUMBER OF VEHICLE
V0LV0	[\$60]	2016–2017		362
V0LV0	[V60]	2016-2017		1, 151
V0LV0	[XC60]	2016–2017		854
V0LV0	[V60CC]	2016-2017		324
			TOTAL	2, 691