VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

(Domestic) Import Vehicles

CAMPAIGN No.	4831	DATE	October 26,2020	
MANUFACTURER	NIPPON TREX CO., LTD.			
	350 Minamiyamashinden, Ina-cho, Toyokawa ctiy, Aichi prefecture, Japan			
DESCRIPTION OF DEFECT	Regarding the spare tire mounting device mounted at wheel base of large van truck, strength of some of said device is insufficient because of inappropriate strength design. Therefore, crack may occur on said device due to the vibration at the time of running, and in the worst case, there is possibility that said part breaks and spare tire mounting device and spare tire will fall, and it may be an obstruct of other traffic.			

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDG-CV5XA	QUON	2012	1
QKG-CD5ZA	QUON	2015	1
QKG-CV5XA	QUON	2016	1
QPG-CD5ZA	QUON	2016-2017	4
QPG-CG5ZE	QUON	2017	1
2PG-CD5CE	QUON	2018	2
LKG-CYE77AZ	GIGA	2012	2
LKG-CYL77A	GIGA	2011-2012	2
QKG-CYL77A	GIGA	2015	1
QKG-CYL77AA	GIGA	2012-2015	8
QKG-CYY77B	GIGA	2017	1
LKG-FU54VZ	FUSO SUPER GREAT	2010-2014	4
LKG-FW1EYBG	HINO PROFIA	2011	1
2PG-FN1AJG	HINO PROFIA	2018	1
2PG-FR1EHG	HINO PROFIA	2018	1
2PG-FW1AHG	HINO PROFIA	2019	7
2RG-FW1AHG	HINO PROFIA	2018	1
		TOTAL	39