## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

CAMPAIGN No. 4882 DATE January 26, 2021

MANUFACTURER Mitsubishi Logisnext Co., Ltd

DESCRIPTION OF DEFECT

Some batteries of the electric forklift have a positive pole made of a material that contains impurities and that causes corrosion made by the combination of specific pole and impurities. If it is continuously used in the state, the pole breaks and electricity is not supplied to the forklift, making it impossible for the forklift to operate in the worst case.

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
ZAF-216E ZAF-288E	「TRINCA」	2018	9 10
ZAF-221E ZAF-241C	「TRANSER」	2018	9 2
F98	「FB15-8」	2018	1
	<u> </u>	TOTAL	31