

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	4975	DATE	June 17, 2021
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		With regard to the brakes for the medium- and heavy-duty trucks, as materials used for plastic pistons in relay valves for parking brakes are inappropriate, the pistons may be hydrolyzed by moisture in the air circuits and damaged by brake air pressure. Consequently, this may potentially lead to air leakage from brake valves, parking brakes being unreleasable, and brake drag.	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QDG-CVR52A	[GIGA]	2017	7
QKG-CVR60B		2016-2017	26
2KG-CVR60C		2017-2019	68
QPG-CVR77B		2017	1
2KG-CVR77C 2PG-CVR77C		2017-2019	7
QKG-CXE60B		2017	5
2KG-CXE60C		2018	3
QKG-CXE77B QPG-CXE77B		2016-2017	37
2KG-CXE77C 2PG-CXE77C		2017-2019	54
QKG-CXG60B		2017	1
2KG-CXG60C		2019	2
2KG-CXG60CT		2018-2019	4
QPG-CXG77B		2016-2017	9
2KG-CXG77C 2PG-CXG77C		2017-2019	52
QKG-CXM60BT		2016-2017	34
2KG-CXM60CT		2017-2019	59
QPG-CXM77B		2016	1

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-CXM77C 2PG-CXM77C	[GIGA]	2018-2019	7
QKG-CXY77BJ QPG-CXY77BJ		2016-2017	37
2KG-CXY77CJ 2PG-CXY77CJ		2017-2019	78
2KG-CXZ60CT		2017-2019	318
QKG-CXZ77AT		2016-2017	176
QKG-CXZ77BT QPG-CXZ77BT		2016-2017	1,112
2KG-CXZ77CT 2PG-CXZ77CT		2017-2019	3,508
QKG-CYE60BM		2016-2017	104
2KG-CYE60CM		2017-2019	220
QKG-CYE77BZ QPG-CYE77BZ		2016-2017	81
2PG-CYE77CZ		2017-2019	12
QKG-CYG60BM		2016-2017	176
2KG-CYG60CM		2017-2019	337
QKG-CYH77B QPG-CYH77B		2016-2017	155
2KG-CYH77C 2PG-CYH77C		2017-2019	265
QKG-CYJ77B QKG-CYJ77BA QPG-CYJ77B QPG-CYJ77BA		2016-2017	4,633
QKG-CYJ77BL QPG-CYJ77BL		2017	7
QKG-CYJ77BZ QPG-CYJ77BZ		2016-2017	14
2KG-CYJ77C 2KG-CYJ77CA 2PG-CYJ77C 2PG-CYJ77CA		2017-2019	10,581
2PG-CYJ77CL		2017-2019	16
2DG-CYJ77CW		2018-2019	35

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-CYJ77CZ 2PG-CYJ77CZ	[GIGA]	2017-2019	69
QFG-CYJ78B		2017-2019	9
QKG-CYL60B		2016-2017	21
2KG-CYL60C		2017-2019	46
QKG-CYL77B QKG-CYL77BA QPG-CYL77B QPG-CYL77BA		2016-2017	2,010
QKG-CYL77BM QPG-CYL77BM		2016-2017	109
QKG-CYL77BZ QPG-CYL77BZ		2016-2017	156
2KG-CYL77C 2KG-CYL77CA 2PG-CYL77C 2PG-CYL77CA		2017-2019	3,436
2KG-CYL77CM 2PG-CYL77CM		2017-2019	262
2KG-CYL77CZ 2PG-CYL77CZ		2017-2019	151
QFG-CYL78B		2017-2018	6
QDG-CYM52AM		2016-2017	10
QKG-CYM77B QPG-CYM77B		2016-2017	91
QKG-CYM77BM QPG-CYM77BM		2016-2017	115
QKG-CYM77BZ		2016-2017	3
2KG-CYM77C 2PG-CYM77C		2017-2019	244
2KG-CYM77CM 2PG-CYM77CM		2017-2019	296
2KG-CYM77CZ 2PG-CYM77CZ		2018-2019	3
QKG-CYY60BY		2016-2017	211
2KG-CYY60CY		2018	1
QKG-CYY77B QPG-CYY77B		2016-2017	189

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QKG-CYY77BJ QPG-CYY77BJ	[GIGA]	2016-2017	31
QKG-CYY77BY QPG-CYY77BY		2016-2017	85
2KG-CYY77C 2PG-CYY77C		2017-2019	329
2KG-CYY77CJ 2PG-CYY77CJ		2017-2019	93
2KG-CYY77CY 2PG-CYY77CY		2017-2019	384
QDG-CYZ52BMQ		2016-2017	57
QDG-CYZ52BV		2016-2017	45
2DG-CYZ52CMQ		2018-2019	80
2DG-CYZ52CV		2018-2019	46
QKG-CYZ77B QPG-CYZ77B		2016-2017	221
QKG-CYZ77BJ QPG-CYZ77BJ		2016-2017	47
QKG-CYZ77BM QPG-CYZ77BM		2016-2017	322
QDG-CYZ77BMQ		2016-2017	3
QDG-CYZ77BV		2016-2017	15
2KG-CYZ77C 2PG-CYZ77C		2017-2019	477
2KG-CYZ77CJ 2PG-CYZ77CJ		2017-2019	146
2KG-CYZ77CM 2PG-CYZ77CM		2017-2019	807
2DG-CYZ77CMQ		2018-2019	4
2DG-CYZ77CV		2018-2019	7
QKG-EXD52BD		2016-2018	2,134
QKG-EXD52BE		2016-2018	558
QKG-EXD52BG		2016-2018	24
2KG-EXD52CD 2PG-EXD52CD		2018-2019	1,295
2KG-EXD52CE 2PG-EXD52CE		2018-2019	345

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-EXD52CG 2PG-EXD52CG	[GIGA]	2018-2019	29
QPG-EXD77BD		2016-2018	81
QKG-EXD77BG QPG-EXD77BG		2016-2018	170
QPG-EXD77BL		2018	1
2PG-EXD77CD		2019	4
2PG-EXD77CG		2018-2019	88
QKG-EXR77BD QPG-EXR77BD		2017-2018	8
QPG-EXR77BG		2017-2018	14
2PG-EXR77CE		2018-2019	6
2PG-EXR77CG		2019	9
QDG-EXY52BJ QKG-EXY52BJ		2016-2018	146
2DG-EXY52CK 2KG-EXY52CK 2PG-EXY52CK		2018-2019	82
QKG-EXY77BJ QPG-EXY77BJ		2016-2018	7
QDG-EXZ52BJ QKG-EXZ52BJ		2016-2018	593
2DG-EXZ52CK 2KG-EXZ52CK 2PG-EXZ52CK		2018-2019	358
2PG-FTR90U2 2PG-FTR90V2 2RG-FTR90U2 2RG-FTR90V2		[FORWARD]	2017-2019
QKG-FVR34U2 QPG-FVR34U2	2016-2017		68
2PG-FVR90U2	2017-2019		123
QDG-FVZ34U2 QKG-FVZ34U2	2016-2017		294
2KG-FVZ60U2	2018-2019		320
2KG-FVZ90U2	2018-2019		41

TYPE	COMMERCIAL NAME	MODELYEAR RECALLED	NUMBER OF VEHICLE
2PG-BTR90U2 2PG-BTR90V2 2RG-BTR90U2 2RG-BTR90V2	[CONDOR]	2017-2019	308
2PG-BVR90U2		2018-2019	13
2KG-BVZ60U2		2018-2019	31
2KG-BVZ90U2		2018-2019	3
		TOTAL	43,702

Vehicles Which Had The Affected Parts Installed After They Rolled Off The Assembly Line

TYPE	COMMERCIAL NAME	MODELYEAR RECALLED	NUMBER OF VEHICLE
LKG-CXE77A QKG-CXE77A	[GIGA]	2010-2015	24
PDG-CXE77X8		2008-2009	3
PJ-CXG51X6		2005	2
LKG-CXG77A QKG-CXG77A		2010-2014	5
PDG-CXG77X8		2008-2009	4
PDG-CXM77K8		2007	2
LKG-CXY77AJ QKG-CXY77AJ		2011-2014	4
PDG-CXY77S8J		2007	1
PDG-CXY77V8J		2007	1
PJ-CXZ51K6		2005-2007	10
PDG-CXZ52K8		2007-2010	4
LKG-CXZ77AT QKG-CXZ77AT		2010-2015	44
QKG-CXZ77BT QPG-CXZ77BT		2015-2016	2
PJ-CXZ77K6		2006-2007	3
PDG-CXZ77K8		2007-2009	5
LKG-CYE77AM QKG-CYE77AM		2011-2015	6
LKG-CYE77AZ QKG-CYE77AZ		2011-2015	11

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PDG-CYE77P8	[GIGA]	2007	2
PDG-CYE77Y8Z		2008	1
QKG-CYG77AM		2013-2016	4
PJ-CYG77P6		2005-2007	5
PDG-CYG77P8		2008	1
PDG-CYG77S8		2010	1
PDG-CYG77Y8Z		2008	1
LKG-CYH77A QKG-CYH77A		2011-2015	14
PDG-CYH77W8		2008-2010	2
PJ-CYJ51W6		2005-2007	12
PJ-CYJ51W6Z		2005-2006	2
PJ-CYJ52W6		2006-2007	2
PDG-CYJ52W8A		2008	1
LKG-CYJ77A LKG-CYJ77AA QKG-CYJ77A QKG-CYJ77AA		2010-2015	343
LKG-CYJ77AL		2011	2
QKG-CYJ77AZ		2014-2015	5
QKG-CYJ77B QPG-CYJ77B		2015-2016	6
PJ-CYJ77W6 PJ-CYJ77W6A		2006-2007	6
ADG-CYJ77W7		2006	7
PDG-CYJ77W8 PDG-CYJ77W8A PKG-CYJ77W8 PKG-CYJ77W8A		2007-2010	68
PDG-CYJ77W8L		2007	1
PJ-CYL51V6		2005-2007	9
PJ-CYL52V6		2006	1
PDG-CYL52V8		2009	1

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LKG-CYL77A LKG-CYL77AA QKG-CYL77A QKG-CYL77AA	[GIGA]	2010-2015	308
LKG-CYL77AM QKG-CYL77AM		2010-2015	3
LKG-CYL77AZ QKG-CYL77AZ		2011-2015	9
QKG-CYL77B QPG-CYL77B		2015-2016	5
PDG-CYL77Q8 PKG-CYL77Q8		2008-2009	2
PJ-CYL77V6		2005-2007	6
ADG-CYL77V7		2006	4
PDG-CYL77V8 PDG-CYL77V8A PKG-CYL77V8 PKG-CYL77V8A		2007-2010	54
PKG-CYL77V8Z		2007	1
PJ-CYM51P6		2005	1
PJ-CYM51Q6		2006	1
PJ-CYM51V6		2007	3
PDG-CYM52V8		2009	1
LKG-CYM77A QKG-CYM77A		2011-2015	10
LKG-CYM77AM		2011	3
PDG-CYM77Q8		2007-2009	2
PDG-CYM77V8		2007-2008	4
PJ-CYY51Q6J		2006	1
PJ-CYY52V6		2006	1
QKG-CYY60BY		2016	1
LKG-CYY77A QKG-CYY77A		2010-2015	17
LKG-CYY77AY QKG-CYY77AY		2011-2015	19
PDG-CYY77V8		2008-2009	3

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
PDG-CYY77V8J	[GIGA]	2007-2010	8	
PJ-CYZ51P6		2005	1	
PJ-CYZ51Q6		2005-2006	2	
PJ-CYZ51V6		2005	2	
PDG-CYZ52P8		2008-2010	3	
PJ-CYZ52V6		2005-2007	4	
PDG-CYZ52V8		2007	1	
LKG-CYZ77A QKG-CYZ77A		2010-2015	25	
LKG-CYZ77AJ QKG-CYZ77AJ		2012-2015	2	
LKG-CYZ77AM QKG-CYZ77AM		2011-2015	20	
LDG-CYZ77AMQ QDG-CYZ77AMQ		2011-2012	2	
LDG-CYZ77AV		2010	1	
PDG-CYZ77Q8		2008	1	
PDG-CYZ77Q8J		2007	1	
PJ-CYZ77V6		2006	1	
PDG-CYZ77V8		2007-2010	7	
LKG-EXD52AD QKG-EXD52AD		2011-2014	7	
LKG-EXR52AE		2011	1	
QDG-EXY52AJ QKG-EXY52AJ		2014-2015	6	
LDG-EXZ52AJ QDG-EXZ52AJ		2010-2015	10	
LKG-FVR34U2 PDG-FVR34U2		[FORWARD]	2008-2011	4
LDG-FVZ34U2 LKG-FVZ34U2 QDG-FVZ34U2 QKG-FVZ34U2			2011-2016	9
		TOTAL	1,205	

The Affected Parts Shipped As Repair Parts, But The Vehicles With Them Installed, Cannot Be Identified.

PARTS NAME	PARTS NO.	SHIPMENT YEAR	NUMBER OF VEHICLE
Relay Valve Repair Kit	1-85576408-0	2016-2019	19
	8-98165977-0	2016-2019	1,298
Relay Valve Assembly	1-48240354-1	2016-2019	414
	8-98091528-0	2016-2019	758
	8-98292213-0	2017-2019	95
		TOTAL	2,584