

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	4981	DATE	June 22, 2021
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	<p>A sticker of the rental company's control number is affixed to the side glass of the cab specification shovel loaders.</p> <p>This case may be non-compliant with safety standards.</p> <p>(Article 29 Window glass standards).</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDM-WA133	「WA40-8」	2017-2020	17
YDM-WA133A	「WA40-8」 「WA50-8」	2016-2020	95
TOTAL			112