

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4995	DATE	Jul. 29. 2021
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain electric parking brakes, because the strength of the cable tip connected to the drive motor is insufficient, the cable tip may be damaged if the parking brake is activated before the vehicle is stopped. Therefore, the power of the drive motor may not be transmitted, causing the warning light to be illuminated and the parking brake to not operate, resulting the stopped vehicle to start moving.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
TSG-XKC605M	[HINO Dutro]	2016~2018	36	
TSG-XKC645M		2016~2018	30	
TSG-XKC655M		2016~2018	66	
TSG-XKU600M		2016~2018	216	
TSG-XKU600X				
TSG-XKU605M		2016~2018	39	
TSG-XKU640M		2016~2018	6	
TSG-XKU645M		2016~2018	7	
TSG-XKU650M		2016~2018	75	
TSG-XKU655M		2016~2018	33	
TSG-XKU700M		2016~2017	53	
TSG-XKU702M		2017~2018	22	
TSG-XKU710M		2016~2018	226	
TSG-XKU712M		2017~2018	159	
TSG-XKU720M		2016~2018	63	
TSG-XKU722M		2017~2018	22	
TKG-XZC600M		2016~2018	1, 188	
TKG-XZC605M		2016~2018	2, 314	
TPG-XZC605M				
TKG-XZC610T		2016~2018	402	
TPG-XZC610T				
TKG-XZC630T		2016~2018	75	
TPG-XZC630T				
TKG-XZC645M	2016~2018	347		
TPG-XZC645M				
TKG-XZC655M	2016~2018	684		
TPG-XZC655M				
TKG-XZC675M	2016~2018	350		
TKG-XZC675T				

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TKG-XZC710M TPG-XZC710M	[HINO Dutro]	2016~2018	200
2KG-XZU600F TKG-XZU600E TKG-XZU600F TKG-XZU600M TKG-XZU600T TKG-XZU600X TPG-XZU600E TPG-XZU600M TPG-XZU600X		2016~2018	6,837
TKG-XZU602F		2017~2018	132
TKG-XZU605M TPG-XZU605M		2016~2018	2,771
TKG-XZU610T TPG-XZU610T		2016~2018	469
TKG-XZU620T TPG-XZU620T		2016~2018	1,497
TKG-XZU630T		2016~2018	275
2KG-XZU640F TKG-XZU640F TKG-XZU640M TPG-XZU640M		2016~2018	612
TKG-XZU642F TPG-XZU642F		2017~2018	267
TKG-XZU645M TPG-XZU645M		2016~2018	737
2KG-XZU650F TKG-XZU650F TKG-XZU650M TPG-XZU650M		2016~2018	888
TKG-XZU652F TKG-XZU652M		2017~2018	320
TKG-XZU655M TPG-XZU655M		2016~2018	1,793
TKG-XZU675M TKG-XZU675T		2016~2018	1,525
TKG-XZU685M		2016~2018	919
TKG-XZU695M		2016~2018	406

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
2KG-XZU700M 2KG-XZU700X TKG-XZU700M TKG-XZU700X TPG-XZU700M	[HINO Dutro]	2016~2018	1,490	
TKG-XZU702M TPG-XZU702M		2017~2018	155	
2KG-XZU710M TDG-XZU710M TKG-XZU710M TPG-XZU710M		2016~2018	3,376	
TDG-XZU712M TKG-XZU712M TPG-XZU712M		2017~2018	1,951	
2KG-XZU720M TDG-XZU720M TKG-XZU720M TPG-XZU720M		2016~2018	2,258	
TDG-XZU722M TKG-XZU722M TPG-XZU722M		2017~2018	1,218	
2KG-XZU730M TDG-XZU730M TKG-XZU730M		2016~2018	363	
TDG-XZU732M		2017~2018	104	
TKG-XZU775M		2016~2018	369	
TSG-XKC605		[Toyota Dyna200]	2016~2018	5
TSG-XKC655		[Toyota Dyna300]	2016	1
TSG-XKU600A		[Toyota Dyna400]	2018	1
TSG-XKU605		[Toyota ToyoaceG25]	2016~2018	3
TSG-XKU650	[Toyota ToyoaceG35]	2017~2018	19	
TSG-XKU655	[Toyota ToyoaceG45]	2016~2017	3	
TSG-XKU700		2017~2018	9	
TSG-XKU710		2017~2018	3	
TSG-XKU712		2018	5	
TSG-XKU720		2016~2017	4	
TSG-XKU722		2018	4	
TKG-XZC600		2018	841	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TKG-XZC605 TPG-XZC605	[Toyota Dyna200] [Toyota Dyna300]	2016~2018	31
TKG-XZC610D TPG-XZC610D	[Toyota Dyna400] [Toyota ToyoaceG25]	2017	3
TKG-XZC645 TPG-XZC645	[Toyota ToyoaceG35] [Toyota ToyoaceG45]	2017~2018	29
TPG-XZC655		2018	19
TKG-XZC675 TKG-XZC675D		2016~2018	190
2KG-XZU600W TKG-XZU600A TKG-XZU600H TKG-XZU600W TPG-XZU600 TPG-XZU600A TPG-XZU600H		2016~2018	487
TKG-XZU602W		2017~2018	8
TKG-XZU605 TPG-XZU605		2016~2018	13
TKG-XZU610D TPG-XZU610D		2017~2018	3
TKG-XZU620D TPG-XZU620D		2016~2018	12
TKG-XZU640 TKG-XZU640W TPG-XZU640		2016~2017	7
TKG-XZU642W		2017	1
TKG-XZU645 TPG-XZU645		2016~2018	24
TKG-XZU650W		2016	3
TKG-XZU655 TPG-XZU655		2017~2018	98
TKG-XZU675 TKG-XZU675D		2016~2018	20
TKG-XZU685		2016~2018	19
TKG-XZU695		2016~2018	74
2KG-XZU700 TKG-XZU700		2016~2018	6
TKG-XZU702		2017	2

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
2KG-XZU710	[Toyota Dyna200]	2016~2018	8	
TDG-XZU710	[Toyota Dyna300]			
TKG-XZU710	[Toyota Dyna400]			
TPG-XZU710	[Toyota ToyoaceG25]			
TKG-XZU712	[Toyota ToyoaceG35]	2017~2018	7	
TPG-XZU712	[Toyota ToyoaceG45]			
2KG-XZU720	[Toyota ToyoaceG25] [Toyota ToyoaceG35] [Toyota ToyoaceG45]	2016~2018	22	
TDG-XZU720				
TKG-XZU720				
TDG-XZU722		2017~2018	20	
TKG-XZU722				
TPG-XZU722				
2KG-XZU730		2018	1	
TDG-XZU732		2018	1	
		TOTAL	39,351	

Vehicles which had the affected parts installed after they rolled off the assembly line.

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TSG-XKU600M	[HINO Dutro]	2013~2015	12
TQG-XKU600X			
TSG-XKU600X			
TQG-XKU650M		2014	1
TQG-XKU655M		2014~2015	2
TSG-XKU655M			
TSG-XKU700M		2015	1
TQG-XKU710M		2013~2016	6
TSG-XKU710M			
TSG-XKU720M		2014	1
TKG-XZC605M		2015~2016	3
TKG-XZC610T		2016	2
TKG-XZC630T		2015	1
TKG-XZC645M		2015	1
TKG-XZC655M		2014~2015	12
TKG-XZC675M		2015	1

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
SKG-XZU600M SKG-XZU600X TKG-XZU600X TKG-XZU600E TKG-XZU600F	[HINO Dutro]	2011~2016	83	
TKG-XZU605M SKG-XZU605M		2012~2015	8	
TKG-XZU610T		2015	1	
TKG-XZU620T		2015~2016	11	
TKG-XZU630T		2015	4	
TKG-XZU640M TKG-XZU640F		2013~2016	6	
TKG-XZU645M		2015	3	
TKG-XZU650M TKG-XZU650F		2013~2015	8	
TKG-XZU655M		2014~2016	8	
TKG-XZU675M TKG-XZU675T		2014~2016	10	
TKG-XZU685M		2013~2015	6	
TKG-XZU695M		2015~2016	2	
TKG-XZU700M TKG-XZU700X		2013~2016	11	
TKG-XZU710M		2013~2016	27	
TKG-XZU720M TDG-XZU720M		2013~2015	16	
TKG-XZU775M		2014	1	
			TOTAL	248

The affected parts shipped as repair parts, but the vehicles with them installed, cannot be identified.

PARTS NAME	PARTS NO.	SHIPMENT YEAR	NUMBER OF PARTS
electric parking brakes	46300-37051	2016~2017	5
	46300-37052	2017~2018	21
	46300-37061	2016~2017	3
	46300-37062	2017~2018	3
	46300-37071	2016~2017	1
	46300-37072	2017~2018	2
		TOTAL	35