## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-3278	DATE	September 2, 2021	
MANUFACTURE	Automobiles CITROEN (Japanese Importer : G	iroupe PSA Japan Co., Lt	d.)	
DESCRIPTION OF DEFECT	The bolt securing front suspension lower arm ball joint and swivel pin may not be properly tightened at manufacturing plant. This may lead the bolt's falling off during vehicles' usage and a loss of vehicle control.			
	The rectification is to fit new bolts and nuts on both right and left hand sides, and tighten them with specified torque.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BA-B6HN05	C3	2020	2
5BA-A8HN05	C3	2020 - 2021	6
	TOTAL		8