VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

| CAMPAIGN No. | 5004 | DATE | Sep. 13. 2021 |
|-----------------------|---|------|---------------|
| MANUFACTURER | Hino Motors, Ltd. | | |
| DESCRIPTION OF DEFECT | On certain metal water tank for toilets of heavy-duty buses, because the strength of the tank fixing part is insufficient, the fixing part may be damaged, causing the tank to fall off. Therefore, the electric wiring for the toilet fixed to the tank may be damaged, resulting in a fire. | | |

| ТҮРЕ | COMMERCIAL | MODEL YEAR | NUMBER OF |
|-------------|---------------|------------|-----------|
| | NAME | RECALLED | VEHICLE |
| BJG-RU1ASAR | [HINO Selega] | 2009 | 4 |
| QQG-RU1ASBR | | 2012~2016 | 10 |
| QRG-RU1ASCA | | 2012~2017 | 141 |
| QTG-RU1ASCA | | | |
| 2TG-RU1ASDA | | 2017~2020 | 150 |
| ADG-RU1ESAA | | 2005~2010 | 189 |
| PKG-RU1ESAA | | | |
| LKG-RU1ESBA | | 2011~2017 | 215 |
| QPG-RU1ESBA | | | |
| QRG-RU1ESBA | | | |
| 2RG-RU1ESDA | | 2017~2020 | 54 |
| | | TOTAL | 763 |

(Remarks) Concerning this case, a recall notification for the provisional measures was submitted with "Notification No. 4828" dated October 16, 2020. Then it was confirmed that the provisional measures are sufficiently effective as permanent measures. Therefore, Hino is switching the measures to permanent measures.