

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	5030	DATE	October 14 ,2021
MANUFACTURER	ISUZU MOTORS LIMITED		
DESCRIPTION OF DEFECT	<p>In certain trucks and buses, inappropriate material is used for the differential-pressure hose connected to the differential-pressure sensor in the exhaust gas emission control device. Therefore, the iodine emitted from this differential-pressure hose corrodes the circuit of the differential-pressure sensor, possibly resulting in the breaking of wire. This triggers the check engine light to turn on and stops controlling the exhaust gas recirculation (EGR) valve, possibly leading to the exhaust gas failing to meet the standard.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-CVR60C	[GIGA]	2017-2019	44
2KG-CVR77C 2PG-CVR77C		2017-2019	3
2KG-CXE60C		2018	1
2KG-CXE77C 2PG-CXE77C		2017-2019	30
2KG-CXG60CT		2019	2
2KG-CXG77C 2PG-CXG77C		2017-2019	22
2KG-CXM60CT		2017-2019	37
2KG-CXM77C 2PG-CXM77C		2018-2019	6
2KG-CXY77CJ 2PG-CXY77CJ		2017-2019	58
2KG-CXZ60CT		2017-2019	180
2KG-CXZ77CT 2PG-CXZ77CT		2017-2019	2,034
2KG-CYE60CM		2017-2019	119
2PG-CYE77CZ		2017-2019	9
2KG-CYG60CM		2017-2019	191

TYPE	COMMERCIAL NAME	MODELYEAR RECALLED	NUMBER OF VEHICLE
2KG-CYH77C 2PG-CYH77C	[GIGA]	2017-2019	191
2KG-CYJ77C 2KG-CYJ77CA 2PG-CYJ77C 2PG-CYJ77CA		2017-2019	5,646
2PG-CYJ77CL		2017-2019	9
2DG-CYJ77CW		2018-2019	20
2KG-CYJ77CZ 2PG-CYJ77CZ		2017-2019	42
2KG-CYL60C		2017-2019	22
2KG-CYL77C 2KG-CYL77CA 2PG-CYL77C 2PG-CYL77CA		2017-2019	1,843
2KG-CYL77CM 2PG-CYL77CM		2017-2019	147
2KG-CYL77CZ 2PG-CYL77CZ		2017-2019	74
2KG-CYM77C 2PG-CYM77C		2017-2019	139
2KG-CYM77CM 2PG-CYM77CM		2017-2019	181
2KG-CYM77CZ 2PG-CYM77CZ		2018-2019	2
2KG-CYY60CY		2018	1
2KG-CYY77C 2PG-CYY77C		2017-2019	182
2KG-CYY77CJ 2PG-CYY77CJ		2017-2019	54
2KG-CYY77CY 2PG-CYY77CY		2017-2019	230
2KG-CYZ77C 2PG-CYZ77C		2017-2019	284
2KG-CYZ77CJ 2PG-CYZ77CJ		2017-2019	96
2KG-CYZ77CM 2PG-CYZ77CM		2017-2019	506
2DG-CYZ77CMQ		2018-2019	3
2DG-CYZ77CV		2018-2019	7

TYPE	COMMERCIAL NAME	MODELYEAR RECALLED	NUMBER OF VEHICLE
2PG-EXD77CD	[GIGA]	2019	3
2PG-EXD77CG		2018-2019	74
2PG-EXR77CE		2018-2019	6
2PG-EXR77CG		2019	6
2KG-FVZ60U2	[FORWARD]	2018-2019	202
2PG-NKR88YN 2RG-NKR88YN	[ELF]	2018	138
2PG-NPR88YN 2RG-NPR88YN		2018	1,290
2KG-BVZ60U2	[CONDOR]	2018-2019	30
		TOTAL	14,164