VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

			Domestic Import Vehicles	
CAMPAIGN No.	5034	DATE	Oct. 18. 2021	
MANUFACTURER	Kawasaki Motors, Ltd.			
DESCRIPTION OF DEFECT	On eligible units, the exhaust pipe might be fixed incompletely due to improper muffler installation. This could lead to loosening of the nuts fixing the exhaust pipe, and in the worst case, the nut and the collar for fixing the exhaust pipe ma fall off.			

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	Notes
2BL-EJ800B	「W800 STREET」 「W800 CAFE」 「W800」 「MEGURO K3」	2019~2021	2,136	
		TOTAL	2,136	