

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	Gai-3316	DATE	November 11, 2021
MANUFACTURE	DS Automobiles (Japanese Importer : Groupe PSA Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	Spacer for rear grab handle may completely detach from the body when curtain air bag deploys. As this result its sharp edges may present to occupant and there is a possibility of injuring occupant due to the sharp edge.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3DA-X74AH01	DS 7	2020 - 2021	105
3LA-X745G06H	DS 7 CROSSBACK E-TENSE	2020 - 2021	48
7BA-X745G06	DS 7	2020 - 2021	41
TOTAL			194