

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ /Import Vehicles

|                       |   |      |                  |
|-----------------------|---|------|------------------|
| CAMPAIGN No.          | Gai-3311  | DATE | 16/November/2021 |
| MANUFACTURER          | Automobiles Volvo Car Corporation<br>(Japanese Importer: Volvo Car Japan Limited)   |      |                  |
| DESCRIPTION OF DEFECT | Clip on the oil cooling pipe in the 7DCTH transmission was removed and vibration from engine and transmission may lead to fatigue cracks of the oil cooling pipe. |      |                  |

| TYPE  | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|-------|-----------------|---------------------|-------------------|
| VOLVO | [ XC40 ]        | 2021                | 29                |
|       |                 | TOTAL               | 29                |