

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

Campaign No.	Gai-3318	Date	Nov X, 2021
Manufacture	CATERPILLAR JAPAN LLC.		
Description of Deffect	Some of the shovel loader axle sun gears do not meet the design intent material. Therefore, if drivers continue to use it, it may be damaged due to insufficient strength, and in the worst case, operators may not be able to drive.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDR-LTE	「926M」	2020	1
		TOTAL	1