

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5063	DATE	Dec.2 2021
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some large-sized intercity express buses, a left rearview mirror with a radius of curvature of 620 mm or 900 mm is installed. Therefore, when the bus is used as a route bus, there is a risk of violating the conductorless bus structural requirements.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QRG-MS96VP	「FUSO AERO ACE」	2012~2015	509
QTG-MS96VP		2015~2017	400
2TG-MS06GP		2017~2021	632
		TOTAL	1,541