

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3321	Date	December 2, 2021
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	Due to the control program of the combination meter is inappropriate, the optical and acoustic warning is deactivated if the driver has fastened themselves in before the person on the rear seat bench has done so, even if there are people on the rear seat bench that are not yet fastened in. Therefore, it may not comply with the requirements of UN regulation number 16.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BA-C1DKR	VW T-CROSS 1.0/85kW	MY2021	23
		Total	23