

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	5080	DATE	24 December , 2021
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	The window glass on some hydraulic wheel loaders with 2-seater cab is not stamped with the symbol (ECE mark) in accordance with Regulation No. 43 due to improper part management. As a result, this window glass may not satisfy Article 29 of Safety Standards (Window Glass Standards).		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDP-WA138	「WA100-8」	2021	28
YDP-WA138	「WA150-8」	2021	24
		TOTAL	52