

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

(Domestic) Import Vehicles

CAMPAIGN No.	5064	DATE	December 1 ,2021
MANUFACTURER	NIPPON TREX CO., LTD. 350 Minamiyamashinden, Ina-cho, Toyokawa ctiy, Aichi prefecture, Japan		
DESCRIPTION OF DEFECT	Regarding the directional indicator of a heavy duty van type truck, the blinking cycle of the operating status indicator on the meter cluster does not change when one of the directional indicators at the front or rear of the vehicle runs out of bulbs due to inappropriate electrical wiring connection of the auxiliary directional indicator mounted on the rear overhang. Therefore, the operating status of the direction indicator cannot be checked from the driver's seat.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2DG-CYJ77CW	GIGA	2021	8
		TOTAL	8