

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5 0 9 6	DATE	Feb. 10. 2022
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	Regarding the muffler, a silencer with the wrong specification may have been installed to the muffler due to improper operation while selecting the silencer in the manufacturing process. This condition may not meet the requirements of the noise regulations.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
3BF-CS8E26	N I S S A N N V 3 5 0 C A R A V A N	2 0 2 1	1 6
3BA-KS6E26			3
3BA-KS8E26			2
		TOTAL	2 1