

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5022	DATE	2022/02/22
MANUFACTURER	KUBOTA Corporation		
DESCRIPTION OF DEFECT	Our sales company stuck identification number stickers of a vehicle rental company on some wheel loaders with cabin. These stickers are stuck both side of the side window glass for identification of vehicle of customer. Those vehicles has possibility that not complying with Article 29 of the window glass safety standard in provisions of the Road Transport Vehicle Act.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
R420D	「R420D」	10055~10134 August 21.2003 to November 7, 2003	3
SA-420D		10274~10942 October 19, 2004 to October 12.2007	24
SA-520D	「R520D」	10173~10458 September 16.2003 to September 28.2006	4
EDM-R430	「R430」	10093~10123 March 22.2007 to October 11 2007	18
	「R430Z」	20134~23453 March 19.2008 to July 31.2015	144
EDM-R530	「R530Z」	20433~21380 April 11.2008 to August 31.2015	6
YDM-R430E	「R430E」	10238~10830 August 8.2017 to September 16.2020	102
YDM-R530E	「R530E」	10133 September 5.2019	1
R430M	「R430M」	30076~31027 September 19.2017 to October 8.2020	17
TOTAL			319

[Notes]

The range of vehicle numbers for recalled vehicles may include vehicles that are not.