

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicle

CAMPAIGN No.	GAI-3168	DATE	Feb 10. 2021
MANUFACTURER	Rosenbauer International AG (Japanese Importer: TEIKOKU SEN-I CO., LTD.)		
DESCRIPTION OF DEFECT	Inappropriate wheel rim manufacturing process and material management for tire wheels of chemical fire engines, some of them are not strong enough. Therefore, if it is continued to use it as it is, the wheel rim is made cracks, and in the worst case, there is a risk that the wheel rim will be damaged and tire will come off.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
Rosenbauer	Panther 6x6	November 1. 2019	VA96WK683KLRB 1077
		December 8. 2019	VA96WJ688KLRB 1103
		November 1. 2019	VA96WK682KLRB 1104
		TOTAL	3