VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAL-3169	DATE	2021/02/10
MANUFACTURER	Tesla, Inc		
MANUFACIURER	(Japanes	e Importer; Tesla Motors Japan)	
	an 8GB embedded Mult Control Unit (MCU) m This may result in a and/or prompt an ale device has degraded	Model X vehicles built i Media Card ("8GB eMM ight malfunction due to blank or intermittentl rt on the MCU display tand to contact Service. ing and defrosting cont	C") in the Media accumulated wear. y blank MCU display hat a memory storage It may lose access

Туре	Commerci al name	MODEL YEAR	Number of
ZAA-SL2S	Model S	RECALLED 2014–2015	Vehicle 106
ZAA-SWL2S	Model S	2015–2016	41
ZAA-SWL1S	Model S	2014-2016	196
ZAA-SL1S	Model S	2014-2016	34
ZAA-SL1S2	Model S	2014–2015	88
ZAA-SWL2S2	Model S	2015	90
ZAA-SL2S2	Model S	2015–2016	39
-	Model S	2016-2018	905
_	Model X	2016-2018	627
Total	2 kinds	2014-2018	2, 126