

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ /Import Vehicles

CAMPAIGN No.	Gai-3164	DATE	18/February/2021
MANUFACTURER	Automobiles Volvo Car Corporation (Japanese Importer: Volvo Car Japan Limited)		
DESCRIPTION OF DEFECT	Filling coolant into the engine cooling system e.g. without using coolant filling vacuum tool or by using a defect coolant filling vacuum tool, could possess a risk for trapped air in the cooling system which might result in insufficient cooling of the engine components. Overheating of engine components which may result in damaged engine components and in rare conditions also cause fire in the engine bay.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
VOLVO	[V40]	2016-2017	3,697
VOLVO	[V40 Cross Country]	2016-2017	1,128
		TOTAL	4,825