VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3346	DATE	March 2, 2022	
MANUFACTURER	Audi			
WANUFACTURER	(Japanese Import	(Japanese Importer: VOLKSWAGEN Grou	Japan K.K.)	
DESCRIPTION OF DEFECT	Incorrect passenger side mirror glass is installed due to improper assembly			
	instructions. The mirror glass is undersized and is not satisfied the legal			
	requirements.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3AA-F1DHUA	Audi RSQ8	2021	110
		Total	110