

第4号様式(英文リコール概要書) (第2関係)

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	5145	DATE	April.25.2022
MANUFACTURER	Onodani Mechanic Co., Ltd.		
DESCRIPTION OF DEFECT	In the mounting of vehicles, the position of the center of gravity may be high when the inside of the packing box is mounted. Therefore, the reference value of the maximum stable tilt angle may not be satisfied, and in the worst case, the vehicle may roll over during traveling.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2RG-XZU605M	HINO Dutro	2021	1
2RG-XZC605M	Toyota Dyna	2021	1
TOTAL			2

(日本工業規格A列4番)