

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3462	DATE	August 15, 2022
MANUFACTURE	Hyundai Motor Company (Japanese Importer : Hyundai Mobility Japan)		
DESCRIPTION OF DEFECT	Due to improper holding of the gas generator, the gas generator will pop out when it explodes. In the worst case, it will hurt passengers.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
Unknown	i30	2021	3
		TOTAL	3