

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	外-3512	DATE	15 th Nov, 2022
MANUFACTURE	Tesla, Inc. (Japanese Importer : Tesla Motors Japan G.K.)		
DESCRIPTION OF DEFECT	There are vehicles with seat belt buckle or a seat belt anchor that is not fastened to correct specifications. It may result in the seat belt system not performing as designed in a crash, which may increase the risk of an injury.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAA-3L13	Model 3	2019-2021	17
ZAA-3L13B		2021	3
ZAA3L23		2019-2021	22
ZAA3L23B		2021	16
ZAA-3L23P		2020-2021	31
ZAA-3L23PB		2021	2
ZAA-3L23T		2022	7
ZAA-3L13T		2022	7
ZAA-3L23PT		2022	1
			TOTAL