## VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

## Domestic Vehicle

| CAMPAIGN No.          | GAI-3563  | DATE | Feb.16,2023 |
|-----------------------|---|------|-------------|
| MANUFACTURER          | TADANO LTD.   |      |             |
| DESCRIPTION OF DEFECT | On some cranes, the vehicle forward camera cable is exposed to the surface of the camera support and therefore does not comply with safety standards. |      |             |

| TYPE        | COMMERCIAL<br>NAME | MODEL<br>YEAR<br>RECALLED | NUMBER OF<br>VEHICLES |
|-------------|--------------------|---------------------------|-----------------------|
| FAUN        | 「ATF-120-5.1」      | 2020 - 2021               | 7                     |
| TADANO FAUN | 「ATF-120-5.1」      | 2021 - 2022               | 21                    |
| FAUN        | 「ATF130G-5」        | 2019 - 2021               | 8                     |
| TADANO FAUN | 「ATF130G-5」        | 2020 - 2022               | 9                     |
| FAUN        | 「ATF200G-5」        | 2018 - 2020               | 9                     |
| TADANO FAUN | 「ATF200G-5」        | 2020 - 2022               | 5                     |
| FAUN        | 「ATF220G-5」        | 2018 - 2020               | 30                    |
| TADANO FAUN | 「ATF220G-5」        | 2020 - 2022               | 18                    |
| TADANO FAUN | 「RTF700-7」         | 2021 - 2022               | 8                     |
|             |                    | TOTAL                     | 115                   |