

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import Vehicles~~

CAMPAIGN No.	Gai-3679	DATE	2023/9/28
MANUFACTURE	Mercedes-Benz AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	<p>On certain CLA (118 platform), A-Class (177 platform), B-Class, GLA, GLB (247 platform) vehicles a functional impairment of the hot-film air mass meter might occur as a result of oil deposits in connection with specific driving profiles.</p> <p>In this case, the oil deposits on the hot-film air mass meter might cause a falsification of the air mass signal and thus lead to a measurement deviation. As a result, the malfunction indicator lamp would illuminate and a limp home mode would be activated. In this case, local legal requirements regarding exhaust emissions might not be met.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
-177084-	A200d	2019	2
3DA-177012			2,060
3DA-177112	A200 Sedan	2020	3,179
3DA-247012	B200d		720
3DA-118312M	CLA200d		2,959
3DA-118612M	CLA200d Shooting Brake		3,271
3DA-247713M	GLA200d 4MATIC	2021	1,673
3DA-247612M	GLB200d		1
		2020	715
		2020	2,110
		TOTAL	16,690