

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	GAI 3671	DATE	22.Sep, 2023
MANUFACTURE	SCANIA CV AB (Japanese Importer: SCANIA JAPANA Co. Ltd. )		
DESCRIPTION OF DEFECT	<p>In wheel nut caps that had been used for anti-corrosion purposes during transport, the vehicle was delivered without the relevant parts being removed due to insufficient instructions for the work to be carried out at the time of delivery.</p> <p>As a result, the wheel nut cap concerned, which is attached to the front axle, protrudes from the vehicle body.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SCANIA	PGRT series Truck	2013-2018	521
		TOTAL	