## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai−3706	DATE	October 18, 2023	
MANUFACTURE	Automobiles CITROEN			
	(Japanese Importer :Stellantis Japan Ltd. )			
DESCRIPTION OF DEFECT	Engine rpm during a safe mode after a failure of accelerator pedal is detected is too high. If a driver leaves the vehicle without stopping engine but keeping the shift at D position, electrical parking brake may not be able to stop the vehicle and the vehicle may move by itself.			

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
5BA-B6HN05	LC37	2020	2
		TOTAL	2