## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3793	DATE	Apr. 4 2024		
MANUFACTURER	Mercedes-Benz (Japanese importer : Mitsubishi Fuso Truck and Bus Corporation )				
DESCRIPTION OF DEFECT	On some articulated buses, the glass attached to the destination sign on the front of the vehicle is improperly bonded, so the adhesive may peel off during use. In the worst case, the glass may fall off.				

ТҮРЕ	COMMERCIAL NAME		MODEL YEAR RECALLED	NUMBER OF VEHICLE
Unclear model	「Citaro-G」	2020~2020		16
		TOTAL	16	