VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	GAI-3902	DATE	Nov.21,2024		
MANUFACTURER	TADANO LTD.				
DESCRIPTION OF DEFECT	On some cranes, air hoses for the parking brake may be damaged by manufacturing defect. Therefore, if the crane is continued to be used as it is, air leak from the hose and the parking brake may not be able to release.				

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED		NUMBER OF VEHICLES
TADANO DEMAG	「AC 5.130-1」	2024		2
			TOTAL	2