## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

## Import Vehicles

CAMPAIGN No.	GAI-3966	Date	March 19, 2025	
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)			
DESCRIPTION OF DEFECT	In the Advanced main-beam control function of LED matrix headlights, due to the inappropriate setting of the light distribution parameters at the production plant, the place where the preceding vehicle or the oncoming vehicle is detected may be irradiated with a high beam instead of a low beam. Therefore, there is a risk that the irradiated light beam will interfere with other traffic, and it does not comply with Japanese regulation.			

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
3BA-A1DPC	T-ROC 1.5/110kW	2024-2025	679
3DA-A1DFF	T-ROC 2.0 TDI/110kW	2025	230
7BA-A1DNFF	T-ROC R 2.0/221kW	2024-2025	78
		Total	987