

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-4041	Date	June 30, 2025
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	In the filter mesh in the inflator (expansion device) of the passenger front airbag, there is a high density of knitting due to an inappropriate manufacturing process. Therefore, when the airbag is deployed, the pressure in the inflator increases, causing the inflator vessel to break, and metal parts may scatter and cause injury.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BA-AWDLA	Polo 1.0/70kW	2024-2025	13
3AA-CJ15V	Passat 1.5 TSI	2025	1
		Total	14