

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Imported Vehicles

CAMPAIGN No.	Gai-4046	DATE	July 31, 2025
MANUFACTURER	RENAULT SAS (Japanese Importer : Renault Japon Co., Ltd.)		
DESCRIPTION OF DEFECT	Some bolt guides for carbon wheels are not strong enough due to insufficient design considerations. As a result, the parts may be cracked due to vibrations while riding, and if continuing to use it in this condition, the parts may break and the bolts may fall off, and in the worst case, the wheel may come off.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
- DFM5P4-	ALPINE A110R	2023	6
		TOTAL	6